


10300693





ROY F. WESTON Region IV TAT

ACTIVITY DESCRIPTION: SITE DIAGRAM

SITE LOCATION CAYCE, MARSHALL COUNTY, MS.

SITE: ENTERPRISE RECOVERY SYSTEMS

TDD NO.: 0492080013


DATE: 25 SEPTEMBER 1992




E.P.A. Region IV  
Weston T.A.T. Activity Location  
TDD# 04-9208-0013  
ENTERPRISE RECOVERY SYSTEMS  
CAYCE, MARSHALL COUNTY, MISSISSIPPI



# hospital route





ROY F. WESTON Region IV TAT

ACTIVITY DESCRIPTION: SITE LOCATION

SITE LOCATION CAYCE, MARSHALL COUNTY, MS.

SITE: ENTERPRISE RECOVERY SYSTEMS

TDD NO.: 0492080013

DATE: 25 SEPTEMBER 1992





PHOTO #1

Official Environmental Protection Agency Photograph

Subject: VIEW OF MAIN OFFICE AND WAREHOUSE

Location: ENTERPRISE RECOVERY SITE  
CAYCE, MARSHALL COUNTY, MS.

TDD#: 0492080013  
Date/Time: 10 SEPTEMBER 1992  
Photographer: VIC YOUNG  
Witness: MICHAEL TAYLOR  
Film: 35 mm / 100 ASA  
Location of Negative: Region 41 - Memphis TAT Office



PHOTO #2

Official Environmental Protection Agency Photograph

Subject: VIEW OF STORAGE TANKS, WAREHOUSE #1 AND #2,  
AND TOWER IN THE MAIN OFFICE

Location: ENTERPRISE RECOVERY SITE  
CAYCE, MARSHALL COUNTY, MS.

TDD#: 0492080013  
Date/Time: 10 SEPTEMBER 1992  
Photographer: VIC YOUNG  
Witness: MICHAEL TAYLOR  
Film: 35 mm / 100 ASA  
Location of Negative: Region 41 - Memphis TAT Office



PHOTO #3

Official Environmental Protection Agency Photograph

Subject: PHOTO OF PIT BEHIND WAREHOUSE,  
SITE OF SAMPLE #9

Location: ENTERPRISE RECOVERY SITE  
CAYCE, MARSHALL COUNTY, MS.

TDD#: 0492080013  
Date/Time: 10 SEPTEMBER 1992  
Photographer: VIC YOUNG  
Witness: MICHAEL TAYLOR  
Film: 35 mm / 100 ASA  
Location of Negative: Region 41 - Memphis TAT Office



PHOTO #4

Official Environmental Protection Agency Photograph

Subject: PHOTO OF DRUM #8 THAT WAS  
SAMPLED IN WAREHOUSE

Location: ENTERPRISE RECOVERY SITE  
CAYCE, MARSHALL COUNTY, MS.

TDD#: 0492080013  
Date/Time: 10 SEPTEMBER 1992  
Photographer: VIC YOUNG  
Witness: MICHAEL TAYLOR  
Film: 35 mm / 100 ASA  
Location of Negative: Region 41 - Memphis TAT Office





PHOTO #5

Official Environmental Protection Agency Photograph

Subject: PHOTO OF UPPER LEVEL OF  
DRUMS IN WAREHOUSE

Location: ENTERPRISE RECOVERY SITE  
CAYCE, MARSHALL COUNTY, MS.

TDD#: 0492080013  
Date/Time: 10 SEPTEMBER 1992  
Photographer: VIC YOUNG  
Witness: MICHAEL TAYLOR  
Film: 35 mm / 100 ASA  
Location of Negative: Region 41 - Memphis TAT Office



PHOTO #6

Official Environmental Protection Agency Photograph

Subject: DISTRIBUTION OF DRUMS  
IN WAREHOUSE

Location: ENTERPRISE RECOVERY SITE  
CAYCE, MARSHALL COUNTY, MS.

TDD#: 0492080013  
Date/Time: 10 SEPTEMBER 1992  
Photographer: VIC YOUNG  
Witness: MICHAEL TAYLOR  
Film: 35 mm / 100 ASA  
Location of Negative: Region 41 - Memphis TAT Office